



www.sunmach.net
 info@sunmach.in
 +91 20 24231345/46

Dimensions of Continuous-Thread Studs

Screw Thread d		M5	M6	M8	M10	M12	M14	M16	M20	M22	M24	M27
P	Pitch	0.8	1	1.25	1.5	1.75	2	2	2.5	2.5	3	3
U	max(=2P)	1.6	2	2.5	3	3.5	4	4	5	5	6	6

Screw Thread d		M30	M36	M42	M48	M56	M64	M72	M80	M90	M100
P	Pitch	3.5	4	4.5	5	5.5	6	6	6	6	6
U	max(=2P)	7	8	9	10	11	12	12	12	12	12

NOTE: ALL DIMENSIONS ARE IN MM.